

## Product Change Notification - GBNG-06TAXU283

**Date:** 28 Feb 2017

**Product Category:** Bluetooth Module

**Notification subject:** CCB 2795 Initial Notice: Qualification of FLCT as a new assembly site for RN41, RN42, RN42N and RN52 Bluetooth module products.

**Notification text:** **PCN Status:**  
Initial notification

**Microchip Parts Affected:**

Please open the attachments found in the attachments field below labeled as PCN\_#\_Affected\_CPN.

NOTE: For your convenience Microchip includes identical files in two formats (.pdf and .xls).

**Description of Change:**

Qualification of FLCT as a new assembly site for RN41, RN42, RN42N and RN52 Bluetooth module products.

**Pre Change:**

Assembled at FCOT assembly site.

**Post Change:**

Assembled at FLCT assembly site.

**Pre and Post Change Summary:**

	Pre Change	Post Change
<b>Assembly Site</b>	FCOT	FLCT

**Impacts to Data Sheet:**

None

**Change Impact:**

None

**Reason for Change:**

To improve productivity by qualifying FLCT as a new assembly site.

**Change Implementation Status:**

In Progress

**Estimated Qualification Completion Date:**

March 24, 2017

Note: Please be advised the qualification completion times may be extended because of unforeseen business conditions however implementation will not occur until after qualification has completed and a final PCN has been issued. The final PCN will include the qualification report and estimated first ship date.

**Time Table Summary:**

	February	March 2017

Workweek	05	06	07	08	09	10	11	12	13
Initial PCN Issue Date					X				
Qualification Report Availability								X	
Final PCN Issue Date								X	

**Method to Identify Change:**

Traceability code

**Qualification Plan:**

Please open the attachments included with this PCN labeled as PCN\_#\_Qual Plan.

**Revision History:**

**February 28, 2017:** Issued initial notification.

The change described in this PCN does not alter Microchip's current regulatory compliance regarding the material content of the applicable products.

**Attachment(s):**

[PCN\\_GBNG-06TAXU283\\_Affected CPN.pdf](#)

[PCN\\_GBNG-06TAXU283\\_Qual Plan.pdf](#)

[PCN\\_GBNG-06TAXU283\\_Affected CPN.xlsx](#)

Please contact your local [Microchip sales office](#) with questions or concerns regarding this notification.

**Terms and Conditions:**

If you wish to change your product/process change notification (PCN) profile please log on to our website at <http://www.microchip.com/PCN> sign into myMICROCHIP to open the myMICROCHIP home page, then select a profile option from the left navigation bar.

To opt out of future offer or information emails (other than product change notification emails), click here to go to [microchipDIRECT](#) and login, then click on the "My account" link, click on "Update profile" and un-check the box that states "Future offers or information about Microchip's products or services."



[Products](#) | [Applications](#) | [Design Support](#) | [Training](#) | [Sample And Buy](#) | [About Us](#) | [Contact Us](#) | [Legal](#) | [Investors](#) | [Careers](#) | [Support](#)

©Copyright 1998-2017 Microchip Technology Inc. All rights reserved.

GBNG-06TAXU283 - CCB 2795 Initial Notice: Qualification of FLCT as a new assembly site for RN41, RN42, RN42N and RN52 Bluetooth module products.

Affected Catalog Part Numbers (CPN)

<b>PCN_GBNG-06TAXU283</b>
<b>Catalog Part Numbers</b>
RN41APL-I/RM536
RN41APL-I/RM550
RN41APL-I/RMCF523
RN41APL-I/RMYAG502
RN41HCI-I/RM
RN41H-I/RM
RN41HID-I/RM
RN41-I/RM
RN41-I/RM
RN41-I/RM477
RN41-I/RM611
RN41-I/RM615
RN41-I/RM630
RN41-I/RMART123R
RN41-I/RMCAR545
RN41-I/RMELAN477
RN41-I/RMEWR616
RN41-I/RMEWR617
RN41-I/RMF477
RN41-I/RMGPS100
RN41-I/RMHID610
RN41-I/RMHID611
RN41-I/RMMGK477
RN41-I/RMPBT100
RN41-I/RMSCT471
RN41-I/RMVTR427
RN41NAPL-I/RM
RN41NAPL-I/RM543
RN41NAPL-I/RM545
RN41SM-I/RM
RN41SMTTL-I/RM
RN41U-I/RM
RN41XVC-I/RM
RN42APL-I/RM
RN42APL-I/RM536
RN42APL-I/RM543
RN42APL-I/RM545
RN42APL-I/RM550
RN42APL-I/RMBRSH543
RN42APL-I/RMFLY502
RN42HCI-I/RM
RN42HID-I/RM
RN42-I/RM

GBNG-06TAXU283 - CCB 2795 Initial Notice: Qualification of FLCT as a new assembly site for RN41, RN42, RN42N and RN52 Bluetooth module products.

Affected Catalog Part Numbers (CPN)

RN42-I/RM477
RN42-I/RM502
RN42-I/RM611
RN42-I/RM615
RN42-I/RM630
RN42-I/RMAIRT127
RN42-I/RMART122
RN42-I/RMART123R
RN42-I/RMART128
RN42-I/RMETI540
RN42-I/RMEVO519
RN42-I/RMEVO519
RN42-I/RMEVO615
RN42-I/RMFB611
RN42-I/RMFLC014
RN42-I/RMFLC111
RN42-I/RMGPO100
RN42-I/RMHID610
RN42-I/RMHID611
RN42-I/RMICP518
RN42-I/RMICP521
RN42-I/RMMGK477
RN42-I/RMPB100
RN42-I/RMPBT100
RN42-I/RMPLX477
RN42-I/RMPLX611
RN42-I/RMSCT471
RN42-I/RMSIO101
RN42-I/RMSQA477
RN42-I/RMVAN611
RN42NAPL-I/RM
RN42NAPL-I/RM545
RN42NAPL-I/RMIWL537
RN42NHCI-I/RM
RN42NHID-I/RM
RN42N-I/RM
RN42N-I/RM477
RN42NU-I/RM
RN42SM-I/RM
RN42SM-I/RM477
RN42U-I/RM
RN42XVP-I/RM
RN42XVU-I/RM
RN52AAC-I/RM
RN52AAC-I/RM116

GBNG-06TAXU283 - CCB 2795 Initial Notice: Qualification of FLCT as a new assembly site for RN41, RN42, RN42N and RN52 Bluetooth module products.

Affected Catalog Part Numbers (CPN)

RN52ACV-I/RM116
RN52ALL-I/RM116
RN52APC-I/RM116
RN52APC-I/RM117
RN52APT-I/RM116
RN52CVC-I/RM116
RN52-I/RM
RN52-I/RM110
RN52-I/RM116
RN52-I/RMEAS116
RN52-I/RMFLX114
RN52-I/RMFLX115
RN52SRC-I/RM100
RN52T-I/RMFLX115
RN52UDF-I/RM116