

Product Change Notification

TE Connectivity

Product Change Notification: E-17-018685 PCN Date: 03-JAN-18

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:
DEUTSCH DTP 4pin series grommet supplier manufacturing location change.

Description of Changes

The Industrial and Commercial Transportation (ICT) business unit of TE Connectivity (TEC) intends to move the molding of the rear wire grommet that is used in the part number(s) listed below from the current supplier USA location to the current supplier Mexico location. We hereby reserve the right to move the tool back to the current supplier USA location as business needs require this. Final assembly of the connectors will remain in ICT-Empalme, Sonora (MX) campus. This PCN is in effect immediately and indefinitely.

Reason for Changes:							
Dear Customer, we inform you of this move of the grommet as part of our aggressive continuous improvement efforts and to meet on time product shipments. An internal							
release based on our specifications will be executed before any parts are delivered. Level 3 PPAP packages by part number assembly will be offered upon customer request.							
Estimated Dates:							
Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):						
	02-FEB-2018						
Last Ship Date (Obsolete Parts Only): Last Date for Mixed Shipments: (Changed Parts Only):							
	31-DEC-2020						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
DTP04-4P	NO			"ZPF000000000130270", "DTP04-4P-AS", "DTP04-4P-SC", "DTP04-4P-S"			
DTP04-4P- C015	NO			"ZPF000000000130271", "DTP04-4P-C015-E"			
DTP04-4P- E003	NO			"ZPF000000000130272", "DTP04-4P-E003-MS", "DTP04-4P-E003-M"			
DTP04-4P- E004	NO			"ZPF000000000130273"			
DTP04-4P- L012	NO			"ZPF00000000130274"			
DTP06-4S	NO			"ZPF000000000130276", "DTP06-4S-AS", "DTP06-4S-SC"			
DTP06-4S- C015	NO			"ZPF000000000130277", "DTP06-4S-C015-LD", "DTP06-4S-C015-LS", "DTP06-4S-C015-E", "DTP06-4S-C015-L"			
DTP06-4S- E003	NO			"ZPF000000000130279", "DTP06-4S-E003-LS", "DTP06-4S-E003-L"			

Part Number(s) being Modified:

Part	Part Discontinued	Customer	Customer Part	Alias Port Number(s)	Substitute Part	Substitute Alias	Description Of
Number	per PCN	Drawing	Number	Alias Part Number(s)	Number	Part Number(s)	Difference
<u>DTP04-4</u> P	NO			"ZPF000000000130270", "DTP04-4P-AS", "DTP04-4P-SC", "DTP04-4P-S"			
DTP04-4P- E004	NO			"ZPF00000000130273"			
	NO			"ZPF000000000130274"			

Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
DTP04-4P- L012							
DTP06-4S	NO			"ZPF000000000130276", "DTP06-4S-AS", "DTP06-4S-SC"			
DTP06-4S- E003	NO			"ZPF000000000130279", "DTP06-4S-E003- LS", "DTP06-4S-E003-L"		_	-

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
DTP04-4P	NO			"ZPF000000000130270", "DTP04-4P-AS", "DTP04-4P-SC", "DTP04-4P-S"		• •	
DTP04-4P- E004	NO			"ZPF00000000130273"			
DTP04-4P- L012	NO			"ZPF00000000130274"			
DTP06-4S	NO			"ZPF000000000130276", "DTP06-4S-AS", "DTP06-4S-SC"			
DTP06-4S- E003	NO			"ZPF000000000130279", "DTP06-4S-E003- LS". "DTP06-4S-E003-L"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Alias Part Number(s)	•
DTP04-4F	NO			"ZPF000000000130270", "DTP04-4P-AS", "DTP04- 4P-SC", "DTP04-4P-S"		
DTP04-4P- C015	NO			ZPF000000000130271", "DTP04-4P-C015-E"		
DTP04-4P- E003	NO			ZPF000000000130272", "DTP04-4P-E003-MS", "DTP04-4P-E003-M"		
DTP04-4P- L012	NO			"ZPF00000000130274"		
DTP06-4S	NO			"ZPF000000000130276", "DTP06-4S-AS", "DTP06- 4S-SC"		
DTP06-4S- C015	NO			"ZPF000000000130277", "DTP06-4S-C015-LD", "DTP06-4S-C015-LS", "DTP06-4S-C015-E", "DTP06-4S-C015-L"		
DTP06-4S- E003	NO			"ZPF000000000130279", "DTP06-4S-E003-LS", "DTP06-4S-E003-L"		

Part Number(s) being Modified:

	r(o) boing woodined.					
Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Alias Part Number(s)	
DTP04-4F	NO			"ZPF000000000130270", "DTP04-4P-AS","DTP04- 4P-SC", "DTP04-4P-S"		
DTP04-4P- C015	NO			'ZPF000000000130271", "DTP04-4P-C015-E"		
DTP04-4P- E003	NO			ZPF000000000130272", "DTP04-4P-E003-MS", "DTP04-4P-E003-M"		

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
DTP04-4P- L012	NO			"ZPF00000000130274"			
DTP06-4S	NO			"ZPF000000000130276", "DTP06-4S-AS", "DTP06- 4S-SC"			
DTP06-4S- C015	NO			"ZPF000000000130277", "DTP06-4S-C015-LD", "DTP06-4S-C015-LS", "DTP06-4S-C015-E", "DTP06-4S-C015-L"			
DTP06-4S- E003	NO			"ZPF00000000130279", "DTP06-4S-E003-LS", "DTP06-4S-E003-L"			