

End Of Life Notice
 Notification – PLC22024
 [26 August 2022]

To: Our Valued Customers

Overview: The purpose of this notification is to communicate that Renesas Electronics has begun the End-of-Life (EOL) Process on select part numbers.

Affected

Products: Attached is a list of products affected by this notification.

Part numbers given in the attached list are for active part numbers in the Renesas Electronics database at the time of this notification.

Key Dates:

Standard Product	
Final Last Time Buy (LTB) Orders placed after this date will not be processed.	26-Feb-23
Last Shipment (LTS)	26-Aug-23
Custom / Proprietary Product	
Final Last Time Buy (LTB) Orders placed after this date will not be processed.	26-Aug-23
Last Shipment (LTS)	26-Feb-24

Response: Please place LTB orders in a timely manner prior to the key dates listed to avoid product availability issues. Shipments between the LTB and LTS dates are Non-Cancelable and Non-Returnable (NCNR).

Renesas Electronics America Inc. will attempt to honor all such purchase orders and scheduled delivery dates, but reserves the right to not accept new orders or to cancel existing orders if such orders cannot be filled through reasonable commercial effort.

Any order resulting from this notice shall be governed by Renesas’s General Terms and Conditions Available at: [General Term and Conditions](#) or the applicable legal terms covering the purchase and sale transaction.

Please work with your sales representative or Field Applications Engineer to determine suitable replacement devices.

Please contact your local sales representative or Central Applications @ 1-888-468-3774 for any questions or comments.

Thank you for your attention.

Sincerely,
 Renesas Electronics



Exact Renesas Part # No other variation is being impacted.	Notice PLC22024 Issue Date	LTB / Withdrawn Date	LTS / Obsolete Date	Replacement / Similar / Re-Design Part Number	Reason
HIP2100IBZT7A	8/26/2022	5/26/2023	11/26/2023	HIP2100IBZT	Manufacturing Discontinuation
HIP2101IBZT7A	8/26/2022	2/26/2023	8/26/2023	HIP2101IBZT	Manufacturing Discontinuation
HIP2103FBZ-T7A	8/26/2022	2/26/2023	8/26/2023	HIP2103FBZ-T	Manufacturing Discontinuation
HIP2103FRTAZ-T7A	8/26/2022	2/26/2023	8/26/2023	HIP2103FRTAZ-T	Manufacturing Discontinuation
HIP2104FRAANZ-T7A	8/26/2022	2/26/2023	8/26/2023	HIP2104FRAANZ-T	Manufacturing Discontinuation
HIP2210FRTZ-T7A	8/26/2022	2/26/2023	8/26/2023	HIP2210FRTZ-T	Manufacturing Discontinuation
HIP2211FBZ-T7A	8/26/2022	2/26/2023	8/26/2023	HIP2211FBZ-T	Manufacturing Discontinuation
HIP2211FR8Z-T7A	8/26/2022	2/26/2023	8/26/2023	HIP2211FR8Z-T	Manufacturing Discontinuation
HIP2211FRTZ-T7A	8/26/2022	2/26/2023	8/26/2023	HIP2211FRTZ-T	Manufacturing Discontinuation
ISL6420BIAZ-T7A	8/26/2022	2/26/2023	8/26/2023	ISL6420BIAZ-TK	Manufacturing Discontinuation
ISL6420BIRZ-T7A	8/26/2022	2/26/2023	8/26/2023	ISL6420BIRZ-TK	Manufacturing Discontinuation
ISL6446IAZ-T7A	8/26/2022	2/26/2023	8/26/2023	ISL6446IAZ-T	Manufacturing Discontinuation
ISL6526AIRZ	8/26/2022	2/26/2023	8/26/2023	None	Manufacturing Discontinuation
ISL6526AIRZ-T	8/26/2022	2/26/2023	8/26/2023	None	Manufacturing Discontinuation
ISL6526AIRZ-TK	8/26/2022	2/26/2023	8/26/2023	None	Manufacturing Discontinuation
ISL6526AIRZ-TKS2779	8/26/2022	8/26/2023	2/26/2024	None	Manufacturing Discontinuation
ISL6526AIRZ-TS2462	8/26/2022	8/26/2023	2/26/2024	None	Manufacturing Discontinuation
ISL6526AIRZ-TS2462S	8/26/2022	8/26/2023	2/26/2024	None	Manufacturing Discontinuation
ISL6526AIRZ-TS2705	8/26/2022	5/26/2023	11/26/2023	None	Manufacturing Discontinuation
ISL6526IRZ	8/26/2022	2/26/2023	8/26/2023	None	Manufacturing Discontinuation
ISL6526IRZ-T	8/26/2022	2/26/2023	8/26/2023	None	Manufacturing Discontinuation
ISL6526IRZ-TK	8/26/2022	2/26/2023	8/26/2023	None	Manufacturing Discontinuation
ISL6526IRZ-TKS2779	8/26/2022	8/26/2023	2/26/2024	None	Manufacturing Discontinuation
ISL6526IRZ-TS2462	8/26/2022	8/26/2023	2/26/2024	None	Manufacturing Discontinuation
ISL6526IRZ-TS2462S	8/26/2022	8/26/2023	2/26/2024	None	Manufacturing Discontinuation
ISL6526IRZ-TS2800	8/26/2022	8/26/2023	2/26/2024	None	Manufacturing Discontinuation
ISL6726AAZ-T7A	8/26/2022	2/26/2023	8/26/2023	ISL6726AAZ-T	Manufacturing Discontinuation
ISL80015AFRZ-T7A	8/26/2022	2/26/2023	8/26/2023	ISL80015AFRZ-T	Manufacturing Discontinuation
ISL80015FRZ-T7A	8/26/2022	2/26/2023	8/26/2023	ISL80015FRZ-T	Manufacturing Discontinuation
ISL80015IRZ-T7A	8/26/2022	2/26/2023	8/26/2023	ISL80015IRZ-T	Manufacturing Discontinuation
ISL80019AFRZ-T7A	8/26/2022	2/26/2023	8/26/2023	ISL80019AFRZ-T	Manufacturing Discontinuation
ISL80019AIRZ-T7A	8/26/2022	2/26/2023	8/26/2023	ISL80019AIRZ-T	Manufacturing Discontinuation
ISL80019FRZ-T7A	8/26/2022	2/26/2023	8/26/2023	ISL80019FRZ-T	Manufacturing Discontinuation
ISL80019IRZ-T7A	8/26/2022	2/26/2023	8/26/2023	ISL80019IRZ-T	Manufacturing Discontinuation
ISL80019IRZ-T7AR5194	8/26/2022	8/26/2023	2/26/2024	ISL80019IRZ-TR5194	Manufacturing Discontinuation
ISL80020AFRZ-T7A	8/26/2022	2/26/2023	8/26/2023	ISL80020AFRZ-T	Manufacturing Discontinuation

ISL80020FRZ-T7A	8/26/2022	2/26/2023	8/26/2023	ISL80020FRZ-T	Manufacturing Discontinuation
ISL8002AFRZ-T7A	8/26/2022	2/26/2023	8/26/2023	ISL8002AFRZ-T	Manufacturing Discontinuation
ISL8002AIRZ-T7A	8/26/2022	2/26/2023	8/26/2023	ISL8002AIRZ-T	Manufacturing Discontinuation
ISL8002BFRZ-T7A	8/26/2022	2/26/2023	8/26/2023	ISL8002BFRZ-T	Manufacturing Discontinuation
ISL8002BIRZ-T7A	8/26/2022	2/26/2023	8/26/2023	ISL8002BIRZ-T	Manufacturing Discontinuation
ISL8002FRZ-T7A	8/26/2022	2/26/2023	8/26/2023	ISL8002FRZ-T	Manufacturing Discontinuation
ISL8002IRZ-T7A	8/26/2022	2/26/2023	8/26/2023	ISL8002IRZ-T	Manufacturing Discontinuation
ISL80030AFRZ-T7A	8/26/2022	2/26/2023	8/26/2023	ISL80030AFRZ-T	Manufacturing Discontinuation
ISL80030FRZ-T7A	8/26/2022	2/26/2023	8/26/2023	ISL80030FRZ-T	Manufacturing Discontinuation
ISL80031AFRZ-T7A	8/26/2022	2/26/2023	8/26/2023	ISL80031AFRZ-T	Manufacturing Discontinuation
ISL80031FRZ-T7A	8/26/2022	2/26/2023	8/26/2023	ISL80031FRZ-T	Manufacturing Discontinuation
ISL8009AIRZ-T7A	8/26/2022	2/26/2023	8/26/2023	ISL8009AIRZ-T	Manufacturing Discontinuation
ISL80101IRAJZ-T7A	8/26/2022	2/26/2023	8/26/2023	ISL80101IRAJZ-T	Manufacturing Discontinuation
ISL80102IRAJZ-T7A	8/26/2022	2/26/2023	8/26/2023	ISL80102IRAJZ-T	Manufacturing Discontinuation
ISL80103IRAJZ-T7A	8/26/2022	2/26/2023	8/26/2023	ISL80103IRAJZ-T	Manufacturing Discontinuation
ISL80111IRAJZ-T7A	8/26/2022	2/26/2023	8/26/2023	ISL80111IRAJZ-T	Manufacturing Discontinuation
ISL80112IRAJZ-T7A	8/26/2022	2/26/2023	8/26/2023	ISL80112IRAJZ-T	Manufacturing Discontinuation
ISL80113IRAJZ-T7A	8/26/2022	2/26/2023	8/26/2023	ISL80113IRAJZ-T	Manufacturing Discontinuation
ISL80121IR50Z-T7A	8/26/2022	2/26/2023	8/26/2023	ISL80121IR50Z-T	Manufacturing Discontinuation
ISL8012IRZ-T7A	8/26/2022	2/26/2023	8/26/2023	ISL8012IRZ-T	Manufacturing Discontinuation
ISL80136IBEAJZ-T7A	8/26/2022	2/26/2023	8/26/2023	ISL80136IBEAJZ-T	Manufacturing Discontinuation
ISL80138IVEAJZ-T7A	8/26/2022	2/26/2023	8/26/2023	ISL80138IVEAJZ-T	Manufacturing Discontinuation
ISL8013AIRZ-T7A	8/26/2022	2/26/2023	8/26/2023	ISL8013AIRZ-T	Manufacturing Discontinuation
ISL8014AIRZ-T7A	8/26/2022	2/26/2023	8/26/2023	ISL8014AIRZ-T	Manufacturing Discontinuation
ISL8016IR12Z-T7A	8/26/2022	2/26/2023	8/26/2023	ISL8016IR12Z-T	Manufacturing Discontinuation
ISL8016IR15Z-T7A	8/26/2022	2/26/2023	8/26/2023	ISL8016IR15Z-T	Manufacturing Discontinuation
ISL8016IR18Z-T7A	8/26/2022	2/26/2023	8/26/2023	ISL8016IR18Z-T	Manufacturing Discontinuation
ISL8016IR25Z-T7A	8/26/2022	2/26/2023	8/26/2023	ISL8016IR25Z-T	Manufacturing Discontinuation
ISL8016IR33Z-T7A	8/26/2022	2/26/2023	8/26/2023	ISL8016IR33Z-T	Manufacturing Discontinuation
ISL8016IRAJZ-T7A	8/26/2022	2/26/2023	8/26/2023	ISL8016IRAJZ-T	Manufacturing Discontinuation
ISL8018IRAJZ	8/26/2022	2/26/2023	8/26/2023	ISL8018IRAJZ-T	Manufacturing Discontinuation
ISL8018IRAJZ-T7A	8/26/2022	2/26/2023	8/26/2023	ISL8018IRAJZ-T	Manufacturing Discontinuation
ISL8018IRAJZ-TS2490	8/26/2022	8/26/2023	2/26/2024	ISL8018IRAJZ-T	Manufacturing Discontinuation
ISL8022IRZ-T7A	8/26/2022	2/26/2023	8/26/2023	ISL8022IRZ-T	Manufacturing Discontinuation
ISL8023AIRTAJZ-T7A	8/26/2022	2/26/2023	8/26/2023	ISL8023AIRTAJZ-T	Manufacturing Discontinuation
ISL8023IRTAJZ-T7A	8/26/2022	5/26/2023	11/26/2023	ISL8023IRTAJZ-T	Manufacturing Discontinuation
ISL8024AIRTAJZ-T7A	8/26/2022	2/26/2023	8/26/2023	ISL8024AIRTAJZ-T	Manufacturing Discontinuation
ISL8024IRTAJZ-T7A	8/26/2022	2/26/2023	8/26/2023	ISL8024IRTAJZ-T	Manufacturing Discontinuation
ISL8025AIRTAJZ-T7A	8/26/2022	2/26/2023	8/26/2023	ISL8025AIRTAJZ-T	Manufacturing Discontinuation

ISL8025IRTAJZ-T7A	8/26/2022	2/26/2023	8/26/2023	ISL8025IRTAJZ-T	Manufacturing Discontinuance
ISL8025IRTAZT7AR5194	8/26/2022	8/26/2023	2/26/2024	ISL8025IRTAJZTKR5194	Manufacturing Discontinuance
ISL8026AFRTAJZ-T7A	8/26/2022	2/26/2023	8/26/2023	ISL8026AFRTAJZ-T	Manufacturing Discontinuance
ISL8026AIRTAJZ-T7A	8/26/2022	2/26/2023	8/26/2023	ISL8026AIRTAJZ-T	Manufacturing Discontinuance
ISL8026FRTAJZ-T7A	8/26/2022	2/26/2023	8/26/2023	ISL8026FRTAJZ-T	Manufacturing Discontinuance
ISL8026IRTAJZ-T7A	8/26/2022	2/26/2023	8/26/2023	ISL8026IRTAJZ-T	Manufacturing Discontinuance
ISL8033IRZ-T7A	8/26/2022	2/26/2023	8/26/2023	ISL8033IRZ-T	Manufacturing Discontinuance
ISL8036IRZ-T7A	8/26/2022	2/26/2023	8/26/2023	ISL8036IRZ-T	Manufacturing Discontinuance
ISL8036IRZ-T7AR5194	8/26/2022	8/26/2023	2/26/2024	ISL8036IRZ-TR5194	Manufacturing Discontinuance
ISL80410IBEZ-T7A	8/26/2022	2/26/2023	8/26/2023	ISL80410IBEZ-T	Manufacturing Discontinuance
ISL80505IRAIZ-T7A	8/26/2022	2/26/2023	8/26/2023	ISL80505IRAIZ-T	Manufacturing Discontinuance
ISL80510IRAIZ-T7A	8/26/2022	2/26/2023	8/26/2023	ISL80510IRAIZ-T	Manufacturing Discontinuance
ISL8088IRZ-T7A	8/26/2022	2/26/2023	8/26/2023	ISL8088IRZ-T	Manufacturing Discontinuance
ISL8117AFRZ-T7A	8/26/2022	2/26/2023	8/26/2023	ISL8117AFRZ-T	Manufacturing Discontinuance
ISL8117FRZ-T7A	8/26/2022	2/26/2023	8/26/2023	ISL8117FRZ-T	Manufacturing Discontinuance
ISL8117FVEZ-T7A	8/26/2022	2/26/2023	8/26/2023	ISL8117FVEZ-T	Manufacturing Discontinuance
ISL8126CRZ-T7A	8/26/2022	2/26/2023	8/26/2023	ISL8126CRZ-T	Manufacturing Discontinuance
ISL8126IRZ-T7A	8/26/2022	2/26/2023	8/26/2023	ISL8126IRZ-T	Manufacturing Discontinuance
ISL8130IAZ-T7A	8/26/2022	2/26/2023	8/26/2023	ISL8130IAZ-TK	Manufacturing Discontinuance
ISL8130IRZ-T7A	8/26/2022	2/26/2023	8/26/2023	ISL8130IRZ-TK	Manufacturing Discontinuance
ISL8130IRZ-T7AR5194	8/26/2022	8/26/2023	2/26/2024	ISL8130IRZ-TK	Manufacturing Discontinuance
ISL81401AFRZ-T7A	8/26/2022	2/26/2023	8/26/2023	ISL81401AFRZ-T	Manufacturing Discontinuance
ISL81401FRZ-T7A	8/26/2022	2/26/2023	8/26/2023	ISL81401FRZ-T	Manufacturing Discontinuance
ISL81601FRZ-T7A	8/26/2022	2/26/2023	8/26/2023	ISL81601FRZ-T	Manufacturing Discontinuance
ISL81601FVEZ-T7A	8/26/2022	2/26/2023	8/26/2023	ISL81601FVEZ-T	Manufacturing Discontinuance
ISL81801FRTZ-T7A	8/26/2022	2/26/2023	8/26/2023	ISL81801FRTZ-T	Manufacturing Discontinuance
ISL81801FVEZ-T7A	8/26/2022	2/26/2023	8/26/2023	ISL81801FVEZ-T	Manufacturing Discontinuance
ISL81802FRTZ-T7A	8/26/2022	2/26/2023	8/26/2023	ISL81802FRTZ-T	Manufacturing Discontinuance
ISL81802FVEZ-T7A	8/26/2022	2/26/2023	8/26/2023	ISL81802FVEZ-T	Manufacturing Discontinuance
ISL8200AMEV1PHZ	8/26/2022	2/26/2023	8/26/2023	None	Manufacturing Discontinuance
ISL8201MEVAL1Z	8/26/2022	2/26/2023	8/26/2023	None	Manufacturing Discontinuance
ISL8202MIRZ-T7A	8/26/2022	2/26/2023	8/26/2023	ISL8202MIRZ-T	Manufacturing Discontinuance
ISL8203MIRZ-T7A	8/26/2022	2/26/2023	8/26/2023	ISL8203MIRZ-T	Manufacturing Discontinuance
ISL8204MEVAL1Z	8/26/2022	2/26/2023	8/26/2023	None	Manufacturing Discontinuance
ISL8205MIRZ-T7A	8/26/2022	2/26/2023	8/26/2023	ISL8205MIRZ-T	Manufacturing Discontinuance
ISL8206MEVAL1Z	8/26/2022	2/26/2023	8/26/2023	None	Manufacturing Discontinuance
ISL8225MEVAL2Z	8/26/2022	2/26/2023	8/26/2023	None	Manufacturing Discontinuance
ISL8225MEVAL3Z	8/26/2022	2/26/2023	8/26/2023	None	Manufacturing Discontinuance
ISL8225MEVAL4Z	8/26/2022	2/26/2023	8/26/2023	None	Manufacturing Discontinuance

ISL8240MEVAL3Z	8/26/2022	2/26/2023	8/26/2023	None	Manufacturing Discontinuation
ISL8240MEVAL4Z	8/26/2022	2/26/2023	8/26/2023	None	Manufacturing Discontinuation
ISL8271MAIRZ-TS2490	8/26/2022	8/26/2023	2/26/2024	None	Manufacturing Discontinuation
ISL85003AFRZ-T7A	8/26/2022	2/26/2023	8/26/2023	ISL85003AFRZ-T	Manufacturing Discontinuation
ISL85003FRZ-T7A	8/26/2022	2/26/2023	8/26/2023	ISL85003FRZ-T	Manufacturing Discontinuation
ISL85003FRZ-T7AR5194	8/26/2022	8/26/2023	2/26/2024	ISL8036IRZ-TR5194	Manufacturing Discontinuation
ISL85005AFRZ-T7A	8/26/2022	2/26/2023	8/26/2023	ISL85005AFRZ-T	Manufacturing Discontinuation
ISL85005FRZ-T7A	8/26/2022	2/26/2023	8/26/2023	ISL85005FRZ-T	Manufacturing Discontinuation
ISL85009FRZ-T7A	8/26/2022	2/26/2023	8/26/2023	ISL85009FRZ-T	Manufacturing Discontinuation
ISL85012FRZ-T7A	8/26/2022	2/26/2023	8/26/2023	ISL85012FRZ-T	Manufacturing Discontinuation
ISL85014FRZ-T7A	8/26/2022	2/26/2023	8/26/2023	ISL85014FRZ-T	Manufacturing Discontinuation
ISL85033IRTZ-T7A	8/26/2022	2/26/2023	8/26/2023	ISL85033IRTZ-T	Manufacturing Discontinuation
ISL85403FRZ-T7A	8/26/2022	2/26/2023	8/26/2023	ISL85403FRZ-T	Manufacturing Discontinuation
ISL854102FRZ-T7A	8/26/2022	2/26/2023	8/26/2023	ISL854102FRZ-T	Manufacturing Discontinuation
ISL85410FRZ-T7A	8/26/2022	2/26/2023	8/26/2023	ISL85410FRZ-T	Manufacturing Discontinuation
ISL85410FRZ-T7AR5194	8/26/2022	8/26/2023	2/26/2024	ISL85410FRZ-TKR5194	Manufacturing Discontinuation
ISL85412FRTZ-T7A	8/26/2022	2/26/2023	8/26/2023	ISL85412FRTZ-T	Manufacturing Discontinuation
ISL85413FRTZ-T7A	8/26/2022	2/26/2023	8/26/2023	ISL85413FRTZ-T	Manufacturing Discontinuation
ISL85413FRTZT7AR5726	8/26/2022	8/26/2023	2/26/2024	ISL85413FRTZ-TR5726	Manufacturing Discontinuation
ISL85415FRZ-T7A	8/26/2022	2/26/2023	8/26/2023	ISL85415FRZ-T	Manufacturing Discontinuation
ISL85415FRZ-TKR5194	8/26/2022	8/26/2023	2/26/2024	ISL85415FRZ-TR5194	Manufacturing Discontinuation
ISL85418FRZ-T7A	8/26/2022	2/26/2023	8/26/2023	ISL85418FRZ-T	Manufacturing Discontinuation
ISL9444IRZ-T7A	8/26/2022	2/26/2023	8/26/2023	ISL9444IRZ-T	Manufacturing Discontinuation
RAA2100404GLG#MD0	8/26/2022	2/26/2023	8/26/2023	RAA2100404GLG#HD0	Manufacturing Discontinuation
RAA2116504GNP#MA0	8/26/2022	2/26/2023	8/26/2023	RAA2116504GNP#HA0	Manufacturing Discontinuation
RAA2116514GNP#MA0	8/26/2022	2/26/2023	8/26/2023	RAA2116514GNP#HA0	Manufacturing Discontinuation
RAA2124214GNP#AA0	8/26/2022	2/26/2023	8/26/2023	RAA2124214GNP#HA0	Manufacturing Discontinuation
RAA2124214GNP#MA0	8/26/2022	2/26/2023	8/26/2023	RAA2124214GNP#HA0	Manufacturing Discontinuation
RAA2124224GNP#AA0	8/26/2022	2/26/2023	8/26/2023	RAA2124224GNP#HA0	Manufacturing Discontinuation
RAA2124224GNP#MA0	8/26/2022	2/26/2023	8/26/2023	RAA2124224GNP#HA0	Manufacturing Discontinuation
RAA214020GNP#MD0	8/26/2022	2/26/2023	8/26/2023	RAA214020GNP#HD0	Manufacturing Discontinuation
RAA2230114GSP#MA0	8/26/2022	2/26/2023	8/26/2023	RAA2230114GSP#HA0	Manufacturing Discontinuation
RAA2230124R0WGSP#AA0	8/26/2022	8/26/2023	2/26/2024	RAA2230124R0WGSP#HA0	Manufacturing Discontinuation
RAA2230214GSP#AA1	8/26/2022	2/26/2023	8/26/2023	RAA2230214GSP#HA1	Manufacturing Discontinuation
RAA2230214GSP#MA1	8/26/2022	2/26/2023	8/26/2023	RAA2230214GSP#HA1	Manufacturing Discontinuation
RTKA210610DE0000BU	8/26/2022	2/26/2023	8/26/2023	None	Manufacturing Discontinuation
RTKA2108252H00000BU	8/26/2022	2/26/2023	8/26/2023	None	Manufacturing Discontinuation
RTKA2108332H00000BU	8/26/2022	2/26/2023	8/26/2023	None	Manufacturing Discontinuation
RTKA2108502H00000BU	8/26/2022	2/26/2023	8/26/2023	None	Manufacturing Discontinuation



RTKA2108702H00000BU	8/26/2022	2/26/2023	8/26/2023	None	Manufacturing Discontinuance
RTKA2109252H00000BU	8/26/2022	2/26/2023	8/26/2023	None	Manufacturing Discontinuance
ZL9010MAIRZ-TR5686	8/26/2022	8/26/2023	2/26/2024	RAA210130GBG#AD0	Manufacturing Discontinuance
ZL9010MAIRZ-TS2490	8/26/2022	8/26/2023	2/26/2024	RAA210130GBG#AD0	Manufacturing Discontinuance
ZL9101EVAL1Z	8/26/2022	2/26/2023	8/26/2023	None	Manufacturing Discontinuance
ZL9117MEVAL1Z	8/26/2022	2/26/2023	8/26/2023	None	Manufacturing Discontinuance