

Product Discontinuance Notice - PDN 22 0083 Rev. -

Analog Devices, Inc. One Analog Way, Wilmington, MA 01887

This notice is to inform you of a product discontinuance for certain ADI products (see Discontinued Parts Material List below). Any issues with this PDN must be sent to ADI as soon as possible. The information contained within this PDN is considered proprietary and should not be shared outside of your company. ADI contact information is listed below.

PDN Title:

Discontinuance of ADA4870ARRZ and ADA4870ARRZ-RL

Publication Date:25-Oct-2022Last Time Buy Date:30-Jun-2023Last Time Ship Date:30-Dec-2024

Revision Description:

Initial Release

Reason For Discontinuance

Products impacted by obsolescence of 20-lead PSOP at assembly vendor

Comments

Replacement part in development but will not be pin-to-pin compatible. See attached PDN package.

Supporting Documents

Attachment 1: Type: Other

ADI_PDN_22_0083_Rev_-_ADA4870 package migration.pdf

	For questions on this PDN, send email to the regional contacts below or contact your local ADI sales representitive						
Americas:	PDN_Americas@analog.com	Europe:	PDN_Europe@analog.com	Japan: Rest of Asia:	PDN_Japan@analog.com PDN_ROA@analog.com		

PDN 22_0083 Discontinued Parts Material List							
Model	Product Family	Replacement Part	Pin To Pin Compatible	Comments			
ADA4870ARRZ	ADA4870	ADA4870ACPZ	No	Replacement part in development, but will not be pin-to-pin compatible.			
ADA4870ARRZ-RL	ADA4870	ADA4870ACPZ-R7	No	Replacement part in development, but will not be pin-to-pin compatible.			

Appendix A - PDN 22_0083 Revision History							
Rev	Publish Date	Rev Description					
Rev	25-Oct-2022	Initial Release					

Analog Devices, Inc. Proprietary Information

Docld:1864 Layout Rev:3 Parent Docld:None