

| | | | |
|--------------------------|-----------------------------|-------------------------------------|---------------------|
| PCN Number: | 20180802001 | PCN Date: | August 08, 2018 |
| Title: | Datasheet for FPC402 | | |
| Customer Contact: | PCN Manager | Dept: | Quality Services |
| Change Type: | | | |
| <input type="checkbox"/> | Assembly Site | <input type="checkbox"/> | Design |
| <input type="checkbox"/> | Assembly Process | <input checked="" type="checkbox"/> | Data Sheet |
| <input type="checkbox"/> | Assembly Materials | <input type="checkbox"/> | Part number change |
| <input type="checkbox"/> | Mechanical Specification | <input type="checkbox"/> | Test Site |
| <input type="checkbox"/> | Packing/Shipping/Labeling | <input type="checkbox"/> | Test Process |
| <input type="checkbox"/> | | <input type="checkbox"/> | Wafer Bump Site |
| <input type="checkbox"/> | | <input type="checkbox"/> | Wafer Bump Material |
| <input type="checkbox"/> | | <input type="checkbox"/> | Wafer Bump Process |
| <input type="checkbox"/> | | <input type="checkbox"/> | Wafer Fab Site |
| <input type="checkbox"/> | | <input type="checkbox"/> | Wafer Fab Materials |
| <input type="checkbox"/> | | <input type="checkbox"/> | Wafer Fab Process |

Notification Details

Description of Change:

Texas Instruments Incorporated is announcing an information only notification. The product datasheet(s) is being updated as summarized below. The following change history provides further details.



FPC402

SNLS582B – JUNE 2017 – REVISED AUGUST 2018

| Changes from Revision A (October 20117) to Revision B | Page |
|---|------|
| • Changed MOD_SDA[0] pin number from: 16 to: 35 | 5 |
| • Changed MOD_SDA[1] pin number from: 5 to: 48..... | 5 |
| • Changed MOD_SDA[2] pin number from: 48 to: 5..... | 5 |
| • Changed MOD_SDA[3] pin number from: 35 to: 16..... | 5 |

The datasheet number will be changing.

| Device Family | Change From: | Change To: |
|---------------|--------------|------------|
| FPC402 | SNLS582A | SNLS582B |

These changes may be reviewed at the datasheet links provided.

<http://www.ti.com/product/FPC402>

Reason for Change:

To accurately reflect device characteristics.

Anticipated impact on Fit, Form, Function, Quality or Reliability (positive / negative):

No anticipated impact. This is a specification change announcement only. There are no changes to the actual device.

Changes to product identification resulting from this PCN:

None.

Product Affected:

| | | | |
|------------|------------|--|--|
| FPC402RHUR | FPC402RHUT | | |
|------------|------------|--|--|

For questions regarding this notice, e-mails can be sent to the regional contacts shown below or your local Field Sales Representative.

| Location | E-Mail |
|--------------|--|
| USA | PCNAmericasContact@list.ti.com |
| Europe | PCNEuropeContact@list.ti.com |
| Asia Pacific | PCNAsiaContact@list.ti.com |
| Japan | PCNJapanContact@list.ti.com |