



Product Change Notification

TE Connectivity

Product Change Notification: E-19-011155

PCN Date: 18-JUL-19

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

SR6 / V23050 6 pole Force Guided Relay

Description of Changes

As of July 15th 2019, TE Connectivity's SR6 6 pole Force Guided Relay has regained the approval to carry the China Compulsory Certificate (CCC) mark of product certification. Starting with Datecode 1930, all eligible SR6 Relays produced thereafter will have the CCC mark printed on them.

Reason for Changes:

Document Clarification. The product has passed the new Implementation Rules for Compulsory Certification by the Chinese Certification and Accreditation Authority (CNCA), and is thus allowed to carry the CCC mark again.

Estimated Dates:

Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
	19-JUL-2019
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	No Mixed Shipments

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-1393260-3	NO			"V23050-A1110-A542", "V23050A1110A542"			
1393260-4	NO			"V23050-A1012-A542", "V23050A1012A542"			
1393260-7	NO			"V23050-A1024-A542", "V23050A1024A542"			
1415015-1	NO			"V23050-A1024-A533", "V23050A1024A533"			
3-1415018-1	NO			"V23050-A1021-A533", "V23050A1021A533"			
3-1415353-1	NO			"SR6M4024"			
5-1415019-1	NO			"V23050-A1110-A551", "V23050A1110A551"			
6-1415027-1	NO			"SR6D4024"			
6-1415537-5	NO			"SR6A6K24"			
8-1415537-0	NO			"SR6B6K24"			
9-1415018-1	NO			"V23050-A1110-A533", "V23050A1110A533"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-1393260-3	NO			"V23050-A1110-A542", "V23050A1110A542"			
1393260-4	NO			"V23050-A1012-A542", "V23050A1012A542"			
1393260-7	NO			"V23050-A1024-A542", "V23050A1024A542"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1415015-1	NO			"V23050-A1024-A533", "V23050A1024A533"			
3-1415018-1	NO			"V23050-A1021-A533", "V23050A1021A533"			
3-1415353-1	NO			"SR6M4024"			
5-1415019-1	NO			"V23050-A1110-A551", "V23050A1110A551"			
6-1415027-1	NO			"SR6D4024"			
6-1415537-5	NO			"SR6A6K24"			
8-1415537-0	NO			"SR6B6K24"			
9-1415018-1	NO			"V23050-A1110-A533", "V23050A1110A533"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-1393260-3	NO			"V23050-A1110-A542", "V23050A1110A542"			
1393260-4	NO			"V23050-A1012-A542", "V23050A1012A542"			
1393260-7	NO			"V23050-A1024-A542", "V23050A1024A542"			
1415015-1	NO			"V23050-A1024-A533", "V23050A1024A533"			
3-1415018-1	NO			"V23050-A1021-A533", "V23050A1021A533"			
3-1415353-1	NO			"SR6M4024"			
5-1415019-1	NO			"V23050-A1110-A551", "V23050A1110A551"			
6-1415027-1	NO			"SR6D4024"			
6-1415537-5	NO			"SR6A6K24"			
8-1415537-0	NO			"SR6B6K24"			
9-1415018-1	NO			"V23050-A1110-A533", "V23050A1110A533"			