

Product Obsolescence Memo

TISP® THYRISTOR SURGE PROTECTORS



February, 2013 (REVISED JULY, 2013)

Select TISP® Thyristor Surge Protectors to be Discontinued

In accordance with our ongoing product lifecycle management procedure, Bourns has identified select TISP® Thyristor Surge Protector products that will be transferred to an *End of Product Life* status. A lack of sales volume and diminishing demand necessitates this action.

Bourns is discontinuing the products listed below, with an effective date of January 31, 2014. For replacement options please contact the Bourns team of Field Application Engineers to review alternative solutions that will meet the application requirements.

Obsolete Part Numbers

BD239-S	BD244A-S	BD652-S	BDT61-S	BDW64-S	BDX33D-S	R3672-S	TIP41A-S	TIP126-S	TIC108N-S
BD239A-S	BD244B-S	BD743-S	BDT61A-S	BDW64A-S	BDX34-S	R3673-S	TIP41B-S	TIP127-S	TIC108S-S
BD239B-S	BD244C-S	BD743A-S	BDT61B-S	BDW64B-S	BDX34A-S	R3674-S	TIP41C-S	TIP130-S	TIC116D-S
BD239C-S	BD539-S	BD743B-S	BDT61C-S	BDW64C-S	BDX34B-S	R3686-S	TIP42-S	TIP131-S	TIC116M-S
BD239D-S	BD539A-S	BD743C-S	BDW23-S	BDW64D-S	BDX34BS-S	TIP29-S	TIP42A-S	TIP132-S	TIC116N-S
BD239E-S	BD539B-S	BD744-S	BDW23A-S	BDW73-S	BDX34C-S	TIP29A-S	TIP42B-S	TIP135-S	TIC116S-S
BD239F-S	BD539C-S	BD744A-S	BDW23B-S	BDW73A-S	BDX34D-S	TIP29B-S	TIP42C-S	TIP136-S	TIC126D-S
BD240-S	BD539D-S	BD744B-S	BDW23C-S	BDW73B-S	BDX53-S	TIP29C-S	TIP47-S	TIP137-S	TIC126M-S
BD240A-S	BD540-S	BD744C-S	BDW24-S	BDW73C-S	BDX53A-S	TIP29D-S	TIP48-S	TIP150-S	TIC126N-S
BD240B-S	BD540A-S	BD895-S	BDW24A-S	BDW73D-S	BDX53B-S	TIP29E-S	TIP49-S	TIP151-S	TIC126S-S
BD240C-S	BD540B-S	BD895A-S	BDW24B-S	BDW74-S	BDX53C-S	TIP29F-S	TIP50-S	TIP152-S	TICC107MR-S
BD241-S	BD540C-S	BD896-S	BDW24C-S	BDW74A-S	BDX54-S	TIP30-S	TIP100-S	TIPL760-S	FVC3100-BK
BD241A-S	BD543-S	BD896A-S	BDW53-S	BDW74B-S	BDX54A-S	TIP30A-S	TIP101-S	TIPL760A-S	FVC2300-BK
BD241B-S	BD543A-S	BD897-S	BDW53A-S	BDW74C-S	BDX54B-S	TIP30B-S	TIP102-S	TIPL760B-S	2EL2
BD241C-S	BD543B-S	BD897A-S	BDW53B-S	BDW74D-S	BDX54C-S	TIP30C-S	TIP105-S	TIPL760C-S	2EL3
BD241D-S	BD543C-S	BD898-S	BDW53C-S	BDW93-S	BF64-S	TIP31-S	TIP106-S	TIPL761B-S	2EL4
BD241E-S	BD544-S	BD898A-S	BDW53D-S	BDW93A-S	BF65-S	TIP31A-S	TIP107-S	TIPL761C-S	2EL5
BD241F-S	BD544A-S	BD899-S	BDW54-S	BDW93B-S	BU406-S	TIP31B-S	TIP110-S	TIPL770-S	4LB1-37603
BD242-S	BD544B-S	BD899A-S	BDW54A-S	BDW93C-S	BU407-S	TIP31C-S	TIP111-S	TIPL791-S	4LB2-37604
BD242A-S	BD544C-S	BD900-S	BDW54B-S	BDW94-S	BUT11-S	TIP31D-S	TIP112-S	TIPL791A-S	4LB3-37605
BD242B-S	BD645-S	BD900A-S	BDW54C-S	BDW94A-S	BUX84-S	TIP31E-S	TIP115-S	TIPL791AS-S	4LB4-37606
BD242C-S	BD646-S	BD901-S	BDW54D-S	BDW94B-S	IDM1-S	TIP31F-S	TIP116-S	TIC106D-S	
BD243-S	BD647-S	BD902-S	BDW63-S	BDW94C-S	IDM1J-S	TIP32-S	TIP117-S	TIC106M-S	
BD243A-S	BD648-S	BDT60-S	BDW63A-S	BDX33-S	R3331T-S	TIP32A-S	TIP120-S	TIC106N-S	
BD243B-S	BD649-S	BDT60A-S	BDW63B-S	BDX33A-S	R3439-S	TIP32B-S	TIP121-S	TIC106S-S	
BD243C-S	BD650-S	BDT60B-S	BDW63C-S	BDX33B-S	R3598-S	TIP32C-S	TIP122-S	TIC108D-S	
BD244-S	BD651-S	BDT60C-S	BDW63D-S	BDX33C-S	R3671-S	TIP41-S	TIP125-S	TIC108M-S	

Products purchased during this *End of Product Life* transition period will be covered by Bourns' standard warranty. Last Time Buy orders for these products will be considered non-cancellable and non-returnable.

Please plan for the following deadlines:

Last Time Buy Date: September 27, 2013

Last Time Ship Date: January 31, 2014

If you have any questions or need additional information, please feel free to contact Customer Service/Inside Sales.

Note: Products in RED have been added.

TSP1301 REV.