



## End Of Life Notice

<b>Issue Date</b>	Nov 6, 2018			
<b>Supplier Name</b>	PULSE ELECTRONICS			
<b>Originator</b>	<b>Name</b>	<b>Email</b>	<b>Phone</b>	
	Levene Xu	<a href="mailto:levenexu@pulseelectronics.com">levenexu@pulseelectronics.com</a>	+86 769 8553 8871 – 2417	
<b>Customer Name</b>	GENERIC			
<b>EOL notice Number</b>	PCN-100000120 Rev A			
<b>Reason for End Of Life</b>	Due the parts have no demand or few demand in recent three years, and the supplier EOL for non-standard capacitor component. Pulse decide to proceed end of life for these part numbers.			
<b>Last Time Buy Date</b>	Based on current backlog and the inventory of capacitor, it can support the last time buy quantity of each part in below for detail, the quantity will be reduced if new order received.			
<b>Warranty</b>	Pulse warranty will be limited to <u>credit only</u> for confirmed defective units.			
<b>Customer Part Number</b>	<b>Pulse Part Number</b>	<b>Pulse replacement part Number</b>	<b>Last Time Buy Date</b>	<b>Last shipment date</b>
	78Z1122B-01NL	No direct replacement identified. Please contact your Pulse product marketing representative.	Not available	
	E2001QNL	No direct replacement identified. Please contact your Pulse product marketing representative.	Not available	
	E2003QNL	No direct replacement identified. Please contact your Pulse product marketing representative.	Not available	
	E2003QNL T	No direct replacement identified. Please contact your Pulse product marketing representative.	Not available	
	E2007QNL	No direct replacement identified. Please contact your Pulse product marketing representative.	Can support 1700pcs	
	E2007QNL T	No direct replacement identified. Please contact your Pulse product marketing representative.		
	E2010	No direct replacement identified. Please contact your Pulse product marketing representative.	Can support 24pcs	
	EX2001	No direct replacement identified. Please contact your Pulse product marketing representative.	Can support 32,000pcs	
	EX2001 T	No direct replacement identified. Please contact your Pulse product marketing representative.		
	EX2001NL	No direct replacement identified. Please contact your Pulse product marketing representative.	Can support 4,000pcs	

	EX2001NLT	No direct replacement identified. Please contact your Pulse product marketing representative.		
	EX2001QNL	No direct replacement identified. Please contact your Pulse product marketing representative.	Can support 1500pcs	
	EX2001QNL	No direct replacement identified. Please contact your Pulse product marketing representative.		
	FL1066NL	No direct replacement identified. Please contact your Pulse product marketing representative.	Can support 314pcs	
	PE-68025QNL	No direct replacement identified. Please contact your Pulse product marketing representative.	Can support 9000pcs	
	PE-68025QNL	No direct replacement identified. Please contact your Pulse product marketing representative.		
	PE-68026NL	No direct replacement identified. Please contact your Pulse product marketing representative.	Can support 35,000pcs	
	PE-68026NLT	No direct replacement identified. Please contact your Pulse product marketing representative.		
	PE-68026QNL	No direct replacement identified. Please contact your Pulse product marketing representative.	Can support 36,000pcs	
	PE-68026QNL	No direct replacement identified. Please contact your Pulse product marketing representative.		
	PE-68027QNL	No direct replacement identified. Please contact your Pulse product marketing representative.	Can support 3000pcs	
	PE-68027QNL	No direct replacement identified. Please contact your Pulse product marketing representative.		
	PE-68056NL	No direct replacement identified. Please contact your Pulse product marketing representative.	Can support 15000pcs	
	PE-68056NLT	No direct replacement identified. Please contact your Pulse product marketing representative.		
	PE-68056QNL	No direct replacement identified. Please contact your Pulse product marketing representative.	Can support 15500pcs	
	PE-68056QNL	No direct replacement identified. Please contact your Pulse product marketing representative.		
	PE-01005FB100JT	No direct replacement identified. Please contact your Pulse product marketing representative.	Not available	
	PE-01005FB121ST	No direct replacement identified. Please contact your Pulse product marketing representative.	Not available	
	PE-01005FB700ST	No direct replacement identified. Please contact your Pulse product marketing representative.	Not available	
	PE-01005FB750STA	No direct replacement identified. Please contact your Pulse product marketing representative.	Not available	
	PE-0201FB220ST	No direct replacement identified. Please contact your Pulse product marketing representative.	Not available	
	PE-0201FB330ST	No direct replacement identified. Please contact your Pulse product marketing representative.	Not available	
	PE-403MCMC900ST	No direct replacement identified. Please contact your Pulse product marketing representative.	Not available	
	PE-01005FB121STA	No direct replacement identified. Please contact your Pulse product marketing representative.	Not available	

---

**Customer acknowledgement/Date**