

CUSTOMER OPERATIONS 160 RIO ROBLES SAN JOSE, CA 95134 PDN #: M000934I

DATE: 24-Oct-2017

PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommeded Replacement	Last Order Date	Last Delivery Date	Reason
Reactivation	DS4404EVKIT#	N/A			Part reactivated from prior notice: M000907I
Reactivation	MAX9140AAXK/V+T	N/A			Part reactivated from prior notice: M000849
Discontinuance	DS1955B+WB5	N/A	24-Oct-2017	24-Oct-2017	Part can no longer be manufactured
Discontinuance	MAX414BCPD+	N/A	24-Oct-2017	24-Oct-2017	Part can no longer be manufactured