	201/03	01000	Notificat	ion I	Date:	March 3, 2017
Title: Datasheet update	e for TFP40	1A-Q1				·
Customer Contact: PCN	N Manager	Dept:	Quality Se	ervic	es	
Change Type:		•				
Assembly Site		Design			Waf	er Bump Site
Assembly Process		Data Sheet				er Bump Material
Assembly Materials		Part number change			Wafer Bump Process	
Mechanical Specification	on	Test Site			Waf	er Fab Site
Packing/Shipping/Lab	eling	Test Proces	S		Waf	er Fab Materials
					Waf	er Fab Process
	N	otificatior	n Details			
Description of Change:						
Texas Instruments Incorpo					otifica	tion.
The product datasheet(s) is	s being upc	lated as sumi	marized below			
The following change histor	ry provides	further detai	ls:			
5 5	, ,					is Terris
						TEXAS INSTRUMENTS
TFP401A-Q1						
SLDS190A-NOVEMBER 2012-REVISED FE	BRUARY 2017					www.ti.com
Changes from Original (Novembe	r 2012) to Rev	ision A				Page
Added the Device Information to	hla Din Config	uration and Eurot	ions postion ESD	Doting	o toblo	
 Added the Device Information ta Implementation section, Power \$ 						
Support section, and Mechanica						
 Changed Changed Features Fro 						
Classification Level C3"						1
 Changed the Operating free-air f 						
85°C in the Recommended Ope	-					6
Changed the Thermal Information	n table values					6
The datasheet number will	be changir	ng.				
The datasheet number will Device Family	be changir Chan	ng. Ige From:		Char	nge To):
The datasheet number will Device Family TFP401A-Q1	be changir Chan SLDS	ng. nge From: 5190		Char SLD):
The datasheet number will Device Family TFP401A-Q1 These changes may be rev	be changir Chan SLDS iewed at th	ng. nge From: 5190 ne datasheet l		Char SLD	nge To):
The datasheet number will Device Family TFP401A-Q1 These changes may be rev http://www.ti.com/lit/ds/sy	be changir Chan SLDS iewed at th	ng. nge From: 5190 ne datasheet l		Char SLD	nge To):
The datasheet number will Device Family TFP401A-Q1 These changes may be rev http://www.ti.com/lit/ds/sy Reason for Change:	be changir Chan SLDS iewed at th ymlink/tfp4	ng. nge From: 5190 ne datasheet l		Char SLD	nge To):
The datasheet number will Device Family TFP401A-Q1 These changes may be rev http://www.ti.com/lit/ds/sy Reason for Change: To accurately reflect device fu	be changin Chan SLDS iewed at th ymlink/tfp4 nctionality.	ng. nge From: 5190 le datasheet l -01a-q1.pdf	inks provided	Char SLD	nge To S190 /	A
The datasheet number will Device Family TFP401A-Q1 These changes may be rev http://www.ti.com/lit/ds/sy Reason for Change: To accurately reflect device fu Anticipated impact on Fi	be changir Chan SLDS iewed at th ymlink/tfp4 nctionality. it, Form, F	ng. nge From: 5190 ne datasheet l 501a-q1.pdf Function, Qu	inks provided ality or Relia	Char SLD	nge To S190	sitive / negative):
The datasheet number will Device Family TFP401A-Q1 These changes may be rev http://www.ti.com/lit/ds/sy Reason for Change: To accurately reflect device fu Anticipated impact on Fi No anticipated impact. This	be changir Chan SLDS iewed at th ymlink/tfp4 nctionality. it, Form, F	ng. nge From: 5190 ne datasheet l 501a-q1.pdf Function, Qu	inks provided ality or Relia	Char SLD	nge To S190	sitive / negative):
The datasheet number will Device Family TFP401A-Q1 These changes may be rev http://www.ti.com/lit/ds/sy Reason for Change: To accurately reflect device fu Anticipated impact on Fi No anticipated impact. This to the actual device	be changin Chan SLDS iewed at th mlink/tfp4 nctionality. it, Form, F s is a specif	ng. nge From: 5190 1e datasheet l 01a-q1.pdf Sunction, Qu Tication chang	inks provided ality or Relia le announcem	Char SLD	nge Tc S190 y (po only. T	sitive / negative):
The datasheet number will Device Family TFP401A-Q1 These changes may be rev http://www.ti.com/lit/ds/sy Reason for Change: To accurately reflect device fu	be changin Chan SLDS iewed at th mlink/tfp4 nctionality. it, Form, F s is a specif	ng. nge From: 5190 1e datasheet l 01a-q1.pdf Sunction, Qu Tication chang	inks provided ality or Relia le announcem	Char SLD	nge Tc S190 y (po only. T	sitive / negative):
The datasheet number will Device Family TFP401A-Q1 These changes may be rev http://www.ti.com/lit/ds/sy Reason for Change: To accurately reflect device fu Anticipated impact on Fi No anticipated impact. This to the actual device Changes to product iden None.	be changin Chan SLDS iewed at th mlink/tfp4 nctionality. it, Form, F s is a specif	ng. nge From: 5190 1e datasheet l 01a-q1.pdf Sunction, Qu Tication chang	inks provided ality or Relia le announcem	Char SLD	nge Tc S190 y (po only. T	sitive / negative):
The datasheet number will Device Family TFP401A-Q1 These changes may be rev http://www.ti.com/lit/ds/sy Reason for Change: To accurately reflect device fu Anticipated impact on Fi No anticipated impact. This to the actual device Changes to product iden	be changin Chan SLDS iewed at th mlink/tfp4 nctionality. it, Form, F s is a specif	ng. nge From: 5190 1e datasheet l 01a-q1.pdf Sunction, Qu Tication chang	inks provided ality or Relia le announcem	Char SLD	nge Tc S190 y (po only. T	sitive / negative):
The datasheet number will Device Family TFP401A-Q1 These changes may be rev http://www.ti.com/lit/ds/sy Reason for Change: To accurately reflect device fu Anticipated impact on Fi No anticipated impact. This to the actual device Changes to product iden None. Product Affected: TFP401AIPZPRQ1	be changin Chan SLDS iewed at th ymlink/tfp4 nctionality. it, Form, F s is a specif	ng. nge From: 5190 1e datasheet l 01a-q1.pdf unction, Qu fication chang resulting fro	inks provided ality or Relia e announcem om this notif	Char SLD billit ent c	nge To S190, y (po only. T	A sitive / negative): here are no changes
The datasheet number will Device Family TFP401A-Q1 These changes may be rev http://www.ti.com/lit/ds/sy Reason for Change: To accurately reflect device fu Anticipated impact on Fi No anticipated impact. This to the actual device Changes to product iden None. Product Affected: TFP401AIPZPRQ1 For questions regarding thi	be changir Chan SLDS iewed at th ymlink/tfp4 nctionality. it, Form, F s is a specif tification	ng. nge From: 5190 ne datasheet I 01a-q1.pdf cunction, Qu resulting from resulting from mails can be	inks provided ality or Relia e announcem om this notif	Char SLD billit ent c	nge To S190, y (po only. T	A sitive / negative): here are no changes
The datasheet number will Device Family TFP401A-Q1 These changes may be rev http://www.ti.com/lit/ds/sy Reason for Change: To accurately reflect device fu Anticipated impact on Fi No anticipated impact. This to the actual device Changes to product iden None. Product Affected: TFP401AIPZPRQ1 For questions regarding this or your local Field Sales Res	be changir Chan SLDS iewed at th ymlink/tfp4 nctionality. it, Form, F s is a specif tification	ng. nge From: 5190 19 datasheet I 01a-q1.pdf Sunction, Qu Fication chang resulting from -mails can be /e.	inks provided ality or Relia e announcem om this notif	Char SLD billit ent c	nge To S190, y (po only. T	A sitive / negative): here are no changes
The datasheet number will Device Family TFP401A-Q1 These changes may be rev http://www.ti.com/lit/ds/sy Reason for Change: To accurately reflect device fu Anticipated impact on Fi No anticipated impact. This to the actual device Changes to product iden None. Product Affected: TFP401AIPZPRQ1 For questions regarding thi pr your local Field Sales Re Location	be changir Chan SLDS iewed at th ymlink/tfp4 nctionality. it, Form, F s is a specif tification	ng. nge From: 5190 The datasheet I 501a-q1.pdf 501a-	inks provided ality or Relia e announcem om this notif sent to the re Mail	Char SLD bilit ent c icati	nge To S190 Sy (po only. T on: al con	sitive / negative): here are no changes tacts shown below
The datasheet number will Device Family TFP401A-Q1 These changes may be rev http://www.ti.com/lit/ds/sy Reason for Change: To accurately reflect device fu Anticipated impact on Fi No anticipated impact. This to the actual device Changes to product iden None. Product Affected: TFP401AIPZPRQ1 For questions regarding thi or your local Field Sales Re Location USA	be changir Chan SLDS iewed at th ymlink/tfp4 nctionality. it, Form, F s is a specif tification	ng. nge From: 5190 The datasheet I 501a-q1.pdf 501a-	inks provided ality or Relia e announcem om this notif sent to the re Mail AmericasConta	Char SLD billit ent c icati	nge To S190 y (po only. T on: al con	sitive / negative): sitive / negative): There are no changes tacts shown below
The datasheet number will Device Family TFP401A-Q1 These changes may be rev http://www.ti.com/lit/ds/sy Reason for Change: To accurately reflect device fu Anticipated impact on Fi No anticipated impact. This to the actual device Changes to product iden None. Product Affected: TFP401AIPZPRQ1 For questions regarding thi or your local Field Sales Re Location	be changir Chan SLDS iewed at th ymlink/tfp4 nctionality. it, Form, F s is a specif tification	ng. nge From: 5190 re datasheet l 01a-q1.pdf unction, Qu resulting from resulting from resulting from PCN PCN	inks provided ality or Relia e announcem om this notif sent to the re Mail	Char SLD billit ent c icati egion	nge Tc S190, y (po only. T on: al con st.ti.co	sitive / negative): sitive / negative): There are no changes tacts shown below